



HERNANDO COUNTY PROPERTY APPRAISER
STRUCTURE AREA CODES

REPORT: EXTINTAUTO
DATE: 11/26/2021
TIME: 00.05.20
PAGE: 1

DESCRIPTION	CODE	CODE	DESCRIPTION
APARTMENT	APC	AGU	ATTACHED GARAGE UNFINISHED-TP
ATTACHED GARAGE UNFINISHED-TP	AGU	APC	APARTMENT
ATTACHED UTILITY UNFINISHED TP	AUU	ATF	ATTIC FINISHED
ATTACHED UTILITY WOOD - TP	AUW	AUU	ATTACHED UTILITY UNFINISHED TP
ATTIC FINISHED	ATF	AUW	ATTACHED UTILITY WOOD - TP
BASE	BAS	BAS	BASE
BASE ADDN	BSA	BCO	BASE CUT OUT
BASE CUT OUT	BCO	BMF	BASEMENT FINISHED
BASE SEMI FINISHED	BSF	BMU	BASEMENT UNFINISHED
BASEMENT FINISHED	BMF	BSA	BASE ADDN
BASEMENT UNFINISHED	BMU	BSF	BASE SEMI FINISHED
CABANA	CAB	CAB	CABANA
CANOPY	CAN	CAN	CANOPY
CARPORT FINISHED	CPF	CPA	CARPORT WITH ALUM ROOF
CARPORT UNFINISHED	CPU	CPF	CARPORT FINISHED
CARPORT WITH ALUM ROOF	CPA	CPU	CARPORT UNFINISHED
DET UTIL WOOD FLR	DUW	DCF	DETACHED CARPORT FINISHED
DETACHED CARPORT FINISHED	DCF	DCU	DETACHED CARPORT UNFINISHED
DETACHED CARPORT UNFINISHED	DCU	DGF	DETACHED GARAGE FINISHED
DETACHED GARAGE FINISHED	DGF	DGU	DETACHED GARAGE UNATTACHED
DETACHED GARAGE UNATTACHED	DGU	DIN	DINING/BINGO EXLUSION ONLY
DETACHED SEMI FINISHED BASE	DSF	DSF	DETACHED SEMI FINISHED BASE
DETACHED SHED UNFINISHED	DSU	DSU	DETACHED SHED UNFINISHED
DETACHED UTILITY FINISHED	DUF	DUF	DETACHED UTILITY FINISHED
DINING/BINGO EXLUSION ONLY	DIN	DUU	UTILITY UNFINISHED
ENCLOSED PORCH ALUM ROOF	EPA	DUW	DET UTIL WOOD FLR
ENCLOSED PORCH FINISHED	EPF	EPA	ENCLOSED PORCH ALUM ROOF
ENCLOSED PORCH UNFINISHED	EPU	EPF	ENCLOSED PORCH FINISHED
ENCLOSED PORCH WOOD - TP	EPW	EPU	ENCLOSED PORCH UNFINISHED
GARAGE FINISHED	GRF	EPW	ENCLOSED PORCH WOOD - TP
GARAGE UNFINISHED	GRU	GEF	GLASS ENCLOSURE FINISHED
GLASS ENCLOSURE FINISHED	GEF	GRF	GARAGE FINISHED
KITCHEN--EXCLUSION ONLY	KIT	GRU	GARAGE UNFINISHED
LOADING PLATFORM CANOPY	LPC	KIT	KITCHEN--EXCLUSION ONLY
LOADING PLATFORM CANOPY	LPW	LNG	LOUNGE EXLUSION ONLY
LOUNGE EXLUSION ONLY	LNG	LPC	LOADING PLATFORM CANOPY
OFFICE AVERAGE	OFA	LPW	LOADING PLATFORM CANOPY
OFFICE GOOD	OFG	OFA	OFFICE AVERAGE
OPEN PORCH ALUM ROOF	OPA	OFG	OFFICE GOOD
OPEN PORCH FINISHED	OPF	OPA	OPEN PORCH ALUM ROOF
OPEN PORCH UNFINISHED	OPU	OPF	OPEN PORCH FINISHED
OPEN PORCH WOOD FLR	OPW	OPU	OPEN PORCH UNFINISHED
SCREEN PORCH ALUM ROOF	SPA	OPW	OPEN PORCH WOOD FLR
SCREEN PORCH FINISHED	SPF	SPA	SCREEN PORCH ALUM ROOF
SCREEN PORCH UNFINISHED	SPU	SPF	SCREEN PORCH FINISHED
SCREEN PORCH WOOD - TP	SPW	SPN	SERVICE PRODUCTION
SERVICE PRODUCTION	SPN	SPU	SCREEN PORCH UNFINISHED
STORE SALES	SSA	SPW	SCREEN PORCH WOOD - TP
UPPER STORY CUT OUT	USC	SSA	STORE SALES
UPPER STORY FINISHED	USF	USC	UPPER STORY CUT OUT
UPPER STORY HIGH	USH	USF	UPPER STORY FINISHED
UPPER STORY LOW	USL	USH	UPPER STORY HIGH



HERNANDO COUNTY PROPERTY APPRAISER
STRUCTURE AREA CODES

REPORT: EXTINTAUTO
DATE: 11/26/2021
TIME: 00.05.20
PAGE: 2

DESCRIPTION	CODE	CODE	DESCRIPTION
UPPER STORY UNFINISHED	USU	USL	UPPER STORY LOW
UTILITY FINISHED	UTF	USU	UPPER STORY UNFINISHED
UTILITY UNFINISHED	DUU	UTA	UTILITY WITH ALUM ROOF
UTILITY UNFINISHED	UTU	UTF	UTILITY FINISHED
UTILITY WITH ALUM ROOF	UTA	UTU	UTILITY UNFINISHED
VINYL PORCH FINISHED	VPF	VPA	VINYL PORCH WITH ALUM ROOF
VINYL PORCH UNF	VPU	VPF	VINYL PORCH FINISHED
VINYL PORCH WITH ALUM ROOF	VPA	VPU	VINYL PORCH UNF
VINYL PORCH WOOD - TP	VPW	VPW	VINYL PORCH WOOD - TP
WOOD DECK	WDK	WDK	WOOD DECK